Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53		
VIN U5YHM81BLHL226276 Engine number 135896 Manufacturer KIA Vehicle model CEED ESTATE MANUAL First license date 13/06/2017 Country Cyprus 2nd Registration 13/06/2017 Engine Size 1368 Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53	Reg No	MXM610
Engine number 135896  Manufacturer KIA  Vehicle model CEED ESTATE MANUAL  First license date 13/06/2017  Country Cyprus  2nd Registration 13/06/2017  Engine Size 1368  Engine Power 73.60kW  Fuel type UNLEADED  Tank capacity 53	Owner	ASG
Manufacturer KIA Vehicle model CEED ESTATE MANUAL First license date 13/06/2017 Country Cyprus 2nd Registration 13/06/2017 Engine Size 1368 Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53	VIN	U5YHM81BLHL226276
Vehicle model CEED ESTATE MANUAL First license date 13/06/2017 Country Cyprus 2nd Registration 13/06/2017 Engine Size 1368 Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53	Engine number	135896
First license date 13/06/2017 Country Cyprus 2nd Registration 13/06/2017 Engine Size 1368 Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53	Manufacturer	KIA
Country Cyprus 2nd Registration 13/06/2017 Engine Size 1368 Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53	Vehicle model	CEED ESTATE MANUAL
2nd Registration13/06/2017Engine Size1368Engine Power73.60kWFuel typeUNLEADEDTank capacity53	First license date	13/06/2017
Engine Size 1368 Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53	Country	Cyprus
Engine Power 73.60kW Fuel type UNLEADED Tank capacity 53	2nd Registration	13/06/2017
Fuel type UNLEADED Tank capacity 53	Engine Size	1368
Tank capacity 53	Engine Power	73.60kW
	Fuel type	UNLEADED
Current mileage 50540	Tank capacity	53
our end inneage	Current mileage	50540





Status	Ref#	Start Date	Repair Shop	Tasks
Maintenance	9814	03/07/2017	PANTELIS CHARALAMBOUS	BODY AND PAINT REPAIRS
			WAS DRIVING ALONG ROAD TO	
			HARBOUR,LORRY WAS PARKED	
			PULLED OUT TO GO ARUND	
			AND TRUCK US HIT ANOTHER	
			CARDAMAGES:FRONT	
			BUMPER AND FRONT WING	
			P/SIDEDANIEL:RESCUE LINE	
Claims	1892	03/07/2017	ATTENDED	
Maintenance	9962	04/07/2017	REMITONIA	BODY PARTS
Claims	2333	01/10/2017		
Maintenance	13018	31/01/2018	REMITONIA	ELECTRICAL FAULTS
old	SER18	01/02/2018	LCA ASG	Oil Filter, Cabin Filter, ENG. OIL, TYRE PRESURE
Maintenance	25272	01/02/2018	LARNACA ASG GARAGE	FULL SERVICE
Claims	3939	21/07/2018		
Maintenance	16089	26/11/2018	KYRIACOS NIKOLA	BODY AND PAINT REPAIRS
old	SER19	06/02/2019	LCA ASG	Oil Filter, Air Filter, Cabin Filter, ENG. OIL
				PASSENGER SIDE SCRATCH ON FRONT BUMPER
Claims	5478	03/05/2019		NO CHARGE SDW
Expenses	7087	21/06/2019	L.P.A CAR ISNPECTION LTD	MOT renewal
Maintenance	22572	03/12/2019	PANTELIS CHARALAMBOUS	BODY AND PAINT REPAIRS
Maintenance	26235	18/12/2019		SHAMPOO

				FULL SERVICE,OIL CHANGE,WIPERS,WIPER/WASHER ,SPRKS,OIL FILTER,AIR FILTER,CABIN
Maintenance	27320	09/01/2020	PAPHOS ASG GARAGE	FILTER,BRAKE PADS FRONT
Expenses	11603	11/01/2020	CYPRUS HIRE RISK POOL	Insurance
Expenses	9714	11/01/2020	CYPRUS HIRE RISK POOL	Insurance
Maintenance	28330	02/02/2020		POLISH